

Command	Key Combinations	
Extrude	E	
Hole	H	
Press Pull	Q	
Fillet	F	
Move	M	
Toggle Visibility	V	
Toggle Component Color Cycling	Shift + N	
Model Toolbox	S	
Appearance	A	
Compute All	Ctrl + B (Windows) or Command + B (Mac)	
Joint	J	
As-built Joint	Shift + J	
Line	L	
2-point Rectangle	R	
Center Diameter Circle	C	
Trim	T	
Offset	O	
Measure	I	
Project	P	
Normal / Construction	X	
Sketch Dimension	D	
Scripts and Add-ins	Shift + S	
Window Selection	1	
Freeform Selection	2	
Paint Selection	3	
Delete	Del	
System Keyboard Shortcuts	Windows Key Combinations	Mac Key Combinations
Create Version	Ctrl + S	Command + S
Recovery Save	Ctrl + Shift + S	Command + Shift + S
Canvas Selection	Windows Key Combinations	Mac Key Combinations
Pan	Hold Middle Mouse Button	Hold Middle Mouse Button


Canvas Selection	Windows Key Combinations	Mac Key Combinations
Zoom	Roll Middle Mouse Button	Roll Middle Mouse Button
Orbit	Hold Shift + Hold Middle Mouse Button	Hold Shift + Hold Middle Mouse Button
Orbit around point	Hold Shift + Click then Hold Middle Mouse Button	Hold Shift + Click then Hold Middle Mouse Button
Undo	Ctrl + Z	Command + Z
Redo	Ctrl + Y	Command + Y
Copy	Ctrl + C	Command + C
Paste	Ctrl + V	Command + V
Cut	Ctrl + X	Command + X
Sculpt Workspace Selection	Windows Key Combinations	Mac Key Combinations
Grow selection	Shift + Up Arrow	Shift + Up Arrow
Shrink selection	Shift + Down Arrow	Shift + Down Arrow
Loop selection	Alt + P	Control + P
Loop grow selection	Alt + O	Control + O
Ring selection	Alt + L	Control + L
Ring grow selection	Alt + K	Control + K
Ring shrink selection	Alt + J	Control + J
Previous U	Alt + Left Arrow	Control + Command + Left Arrow
Next U	Alt + Right Arrow	Control + Command + Right Arrow
Previous V	Alt + Down Arrow	Control + Command + Down Arrow
Next V	Alt + Up Arrow	Control + Command + Up Arrow
Range selection	Alt + M	Command + M
Invert selection	Alt + N	Command + N
Toggle box mode	Alt + 1	Control + 1
Toggle control frame mode	Alt + 2	Control + 2
Toggle smooth mode	Alt + 3	Control + 3
Select edge ring	Double-click an edge	Double-click an edge
Select face ring	Select two faces then double-click a third face	Select two faces then double-click a third face

Edit Form Command	Windows Key Combinations	Mac Key Combinations
Add geometry	Alt + Drag	Alt + Drag
Add geometry and keep creases	Alt + Ctrl + Drag	Alt + Command + Drag
Render Workspace Command	Windows Key Combinations	Mac Key Combinations
Appearance	A	A
Animate Workspace Command	Windows Key Combinations	Mac Key Combinations
Transform Components	M	M
Auto Explode All Levels	U	U
Manual Explode	E	E
View	U	U
Publish Video	P	P
Simulate Workspace Command	Windows Key Combinations	Mac Key Combinations
New Simulation Study	N	N
Structural Constraint	C	C
Structural Loads	L	L
Force	F	F
Model View	Ctrl + L	Command + L
DOF View	Ctrl + D	Command + D
Groups View	Ctrl + G	Command + G
Results View	Ctrl + R	Command + R
Settings	E	E
Drawing Workspace Command	Windows Key Combinations	Mac Key Combinations
Projected View	P	P
Move	M	M
Delete	Delete	Delete
Center Mark	C	C
Dimension	D	D
Text	T	T
Balloon	B	B

CAM Workspace Command	Windows Key Combinations	Mac Key Combinations
Generate Toolpath	Ctrl + G	Command + G
Duplicate	Ctrl + D	Command + D
Show Log	Ctrl + L	Command + L
Scripts and Add-Ins	Shift + S	Shift + S

Shortcuts for switching workspaces




You can now switch workspaces with CTRL + Leftbracket and CTRL + Rightbracket key combos. This will take you through the next and previous workspace in the order it is listed in the workspace switcher.






**AUTODESK®
FUSION 360™**


Keyboard Sticker Sheet





















⌘+B | Ctrl+B
Compute All

Alt+1   + S 
Box Display Scripts

Alt+3   + J 
Smooth Display As-built Joint

S
Toolbox

J 
Joint

Q  Press Pull	E  Extrude	F  Fillet	H  Hole	M  Move
V  Visibility	SHIFT + N  Component Color Cycling	I  Measure	P  Project	L  Line
X  Normal / Construction	DH  Dimension	C  Center Dia. Circle	R  2-Point Rectangle	T  Trim
1  Window Selection	2  Freeform Selection	3  Paint Selection	A  Appearance	O  Offset